## DNR

## Citation for Non-Compliance Utah Minerals Regulatory Program

Citation #:	MN-2016-68-01
-------------	---------------

Ottali Willerals Regulatory Program 1594 West North Temple, Salt Lake City, UT 84114 Phone: (801) 538-5340 Fax: (801) 359-3940		Permit Number:		S/057/0010				
		Date Issued:		10/08/2016				
<b>✓</b> NOTICE OF	VIOLATION	CESSATIO	N ORDER (CO)		FAILURE TO ABATE CO			
Permittee Name: Pine Ridge Excavation and Landscapes In		Inspector I	Inspector ID and Number: Mike Bradley, #68					
Mine Name: Pine Ridge Rock Products		Date of Inspection: 10/04/2016						
Certified Return Receipt Number: 7013 2250 0000 2316 2842			Date and Time of Service: 10-12-16 3:30pm					
Nature of condition, pra								
Failure to complete r	requirements of Divis	sion Directive iss	ued July 1	2, 2016: Large	hole not b	ackfilled.		
Provisions of Act, regula	ations, or permit violate	d:						
R647-3-112. Failure	to Reclaim							
For Cessation Orders and	Failure to Abate CO's,	check appropriate b	ox(es) below	<b>/:</b>				
This order	requires Cessatio	on of ALL m	ining ac	tivities.				
This order requires Cessation of PORTION(S) of the mining activities.								
Mining activities to be			011(5) 0	T the mining	gactiviti			
	ice, or violation is creating to health or safety of the		Permittee/Operator is/has been conducting mining activities without a Permit.					
Condition, practi	ice, or violation is causing	g or can	Permittee has failed to abate Violation included in					
reasonably be expected to cause significant, imminent environmental harm to land, air, or water resources.			Citation # within time for					
			abatement originally fixed or subsequently extended.					
Abatement/corrective					Abatement	t Times (if applicable)		
Complete all requirer 21, 2016. Failure to r the Division to comp	eclaim by this date m				October 2	8, 2016		
Permittee Representative (Pri		1/1	Mich OGM Represent		Brad	10/11/16 Date		
SEE REVERSE SIDE Of This Form For Instructions And Additional Information								